

**Muir Beach Community Service District
Piping Asset Inventory**

	Function	Size	Type	Zone & Location	install	length, ft	Miles	percent of system	Estimated Life	Remaining Life
1	Trans	4	CICL	Corrected for replacement - Net	1965	5250	1.0	23%	75	22.00
		6	HDPE	Seacape to Lower Tank	2007	250	0.0	1%	100	89.00
				1997 Report Length		5500				NA
2	Trans	4	DICL	at Hwy 1 & PRS	1991	325	0.1	1%	75	48.00
3	Distr	6	AC	High - Seascape Subdivision	1965	6500	1.2	28%	75	22.00
	Distr	6	PVC 900	Seacape Dr to Overlook Tank	2010	300	0.1	1%	100	92.00
4	Distr	6	DICL	High - Seascape Subdivision	1965	260	0.0	1%	75	22.00
5	Distr	6	WSCL	High - Seascape Subdivision High - Seascape Subdivision	1965	200	0.0	1%	75	22.00
6	Distr	6	PVC 900	Starbuck Extension High - Seascape Subdivision	1993	230	0.0	1%	100	75.00
7	Distr	4	PVC	Charlotte's Way High - Seascape Subdivision	1970	1300	0.2	6%	50	2.00
8	Distr	4	PVC 900	Starbuck Extension Low - Bello Beach Subdivision	1993	270	0.1	1%	100	75.00
9	Distr	4	PVC	Corrected for replacement - Net Low - Bello Beach Subdivision	1971	6800	1.3	29%	50	3.00
	Distr	6	PVC 900	Pacific Way Low - Bello Beach Subdivision 1997 Report Length Low - Bello Beach Subdivision	1999	600	0.1	3%	100	81.00
						7400		0%		NA
10	Distr	4	PVC 900	W Sunset to Pacific Way Intertie Low - Bello Beach Subdivision	1992	323	0.1	1%	100	74.00
11	Distr	2	GL	Cove Lane Low - Bello Beach Subdivision	1990					NA
	Distr	6	HDPE	Cove Lane Low - Bello Beach Subdivision	2009	225	0.0	1%	100	91.00
12	Distr	4	PVC 900	Charlotte's Way to Sunset Way intertie	1993	500	0.1	2%	100	75.00
						feet				
					Total	23,333	4.4	miles		